Bill no: 1st and Final.

# MEASUREMENT BOOK

| Date | Full description, etc, of work | Dimensions | | | | Contents | Reference to last Measurement |
|---|---|---|---|---|---|---|---|
| | | Number | Length | Breadth | Depth | | |
| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 |
| | Name of work: Filling of pot holes in road No: 15 T. Dasarahalli | | | | | | |
| | Estimate cost Rs 20.00 Lakhs. | | | | | | |
| | Job code No: 015-22-000001 | | | | | | |
| | AS No: EE/BBMP/DD/AS/34/2021-22 | | | | | | |
| | TS No: EE/BBMP/DD/TS/19/2021-22 | | | | | | |
| | P.O. No: EE/BBMP/PO/91/21-22 dated 04-03-2022 | | | | | | |
| | Agency: Vedavathi Road Cutting Enterprises | | | | | | |
| | Date of Record: 02/05/2022 | | | | | | |

**M. A. R. 57 (Rule 116)**
Measurement Book

**No. B**

564498

Serial No. .....
Name of Work ..... From..... To.....
Name of Contractor of nature of Agency .....
Date of commencement of work .....

| Date | Full description, etc, of work | Dimensions | | | | Contents | Reference to last Measurement | |
|---|---|---|---|---|---|---|---|---|
| | | Number | Length | Breadth | Depth | | | |
| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | |
| 5/10 | Description of road work | Previous measurement Qty | Amount | Present measurement Qty | Rate | Amount | Up to date Measurement Qty | Amount |
| 1) | Providing, laying & spreading & compacting wet mix macadam. cum | — | — | 654.67 | 1672.00 | 1094608=24 | 654.67 | 1094608=24 |
| 2) | Filling pot holes and patch repairs with Bituminous Concrete Sqm | — | — | 1214.94 | 274.00 | 332893=56 | 1214.94 | 332893=56 |
| | | | Sub Total ₹ | | 14,27, | 501=80 | 14,27, | 501=80 |

# MEASUREMENT BOOK

| Date | Full description, etc, of work | Dimensions | | | | Contents | Reference to last Measurement |
|---|---|---|---|---|---|---|---|
| | | Number | Length | Breadth | Depth | | |
| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 |
| | Sub Total Rs | | | 14,27,501=80 | | | 14,27,501=80 |
| | GSTQ 12% Rs | | | 1,71,300=22 | | | 1,71,300=22 |
| | Grand Total Rs | | | 15,98,807=02 | | | 15,98,807=02 |
| | | | | | | | 1598801-00 |

Certificate

1. Certify that the Contractor Completed the work satisfactorily
2. Certify that there is no Unpaid material issue to Contractor
3. Certify that the Contractor cleared all debris & Unused.

Agreed
24/05/22

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಜಿ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಜಿ.ಕೆ ಎಂ.ಪಿ
ಬೆಂಗಳೂರು-560073

**M. A. R. 57 (Rule 116)**
Measurement Book

**No. B**

564199

Serial No. .....

Name of Work ..... From..... To.....

Name of Contractor of nature of Agency .....

Date of commencement of work .....

| Date | Full description, etc, of work | Dimensions | | | | Contents | Reference to last Measurement |
|---|---|---|---|---|---|---|---|
| | | Number | Length | Breadth | Depth | | |
| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 |
| | Audited and submitted for Rs 1598801/-<br>Passed by C[illegible] for Rs 1388264/-<br>(Thirteen Lakhs Eighty Eight Thousand two Hundred and sixty Four only)<br>by adjustment Rs 210537/-<br>Accountants Superintendent<br>B.B.M.P. Dasarahalli Division<br>Exe. Engineer | | | | | Gross → 1598801-00<br>IT → 15988-00<br>LWC → 15988-00<br>CBF → 1599-00<br>Rty → 100448-00<br>FSD → 47964-00<br>CESS → 14275-00<br>SESS → 14275-00<br>Ded(-) 210537-00<br>Net → 1388264-00 | |